

## JK2015/022 nr. test report

***Company name and address***

*Szabó Mihályné e.v.*

*babywea-ring.com*

*6750 Algyő*

*Bartók béla u. 80.*

***Contact person: Fábíán-Szabó Dóra***

***Tel: +36 70 504 5230***

***Email: fabianszdora@gmail.com***

***Test provider name and address***

*Atestor Kft.*

*1016 Budapest*

*Aladár utca 19 fszt. 3.*

***Reference number: JK2015/022***

***Order number: VR0198/2015***

*Date: 2015.10.27.*

---

**1. Customer name and address**

Szabó Mihályné e.v.  
babywea-ring.com  
6750 Algyő

**2. Test**

Tensile test

**3. Sample name**

3 pc. aluminium ring ( $D \approx 77,62$  mm)

**4. Name and address of the testing laboratory**

Széchenyi István University  
Department of Material Science and Technology  
Polymer Technology Laboratory  
H-9023. Győr Egyetem tér 1.

**5. Date of the test**

11.08.2015

**6. Test crew**


Domonkosné Böröcz Adél

**7. Applied standards during the test**

There was no standard or prescribed method .

**8. Applied apparatus**


The test was carried out with a maximum load of 100kN INSTRON 5582 tensile machine.

**9. Tensile charts**

**10. Measurement results**

<b>Specimen number</b>	<b>Fracture strength [N]</b>	<b>Fracture strength [kg]</b>
<b>1.</b>	9287,74	928,774
<b>2.</b>	10104,14	1010,414
<b>3.</b>	7062,61	706,261
<b>average:</b>	<b>8818,16</b>	<b>881,816</b>

Date: 2015.10.27.



Nosztrai Ádám  
Executive director